Amendments to the Drawings:

This attached drawing sheets include changes to FIGS. 3, 4 and 6. In FIG. 3, the lead line for number 34 has been changed to the outer circular groove. In FIGS. 4 and 6, numbers 42, 44 and 46 have been changed to 40, 42 and 44..

REMARKS

This corrects errors in the drawing. The original lead line for number 34 in FIG. 3 was in the wrong place. The inner, middle and outer knockouts are identified by numbers 40, 42 and 44 in FIG. 3, and that same numbering is continued in FIGS. 4 and 6. The specification does not include a number 46 as previously used in FIGS. 4 and 6.

Respectfully submitted,

H Duane Switzer

H. Duane Switzer
Reg. No. 22,431
Jones Day
North Point
901 Lakeside Avenue
Cleveland, OH 44114-1190
216-586-7283

Date: Nov. 21, 2006

OIPE IAP86
NOV 27 2006
PATENT & TRADEMARK OFFICE



FIG.3



FIG.2

lead line for 34 is to the outermost groove (not to the same groove as 32)

OIPE IAP86
NOV 27 2006
PATENT & TRADEMARK OFFICE



FIG.6



FIG.4



FIG.5